

Central Sanitation Facility – Stream Restoration
Regenerative Step Pool Storm Conveyance System
Anne Arundel County Government
Department of Public Works
Watershed, Ecosystem, and Restoration Services




Before Restoration
Severely degraded perennial gully
Photo take by KCI during stream assessment
Severn River Watershed Study (March 2004)



One year after Restoration
Regenerative Step Pool Storm Conveyance System
Photos taken by: Hala Flores (June 1/2011)

Central Sanitation Facility
Before Restoration – at location of cascade looking upstream.



Central Sanitation Facility – Before Restoration



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project



Central Sanitation Facility– After Restoration
Chronologically listed from most upstream to downstream limits of project

