

Little Patuxent River Watershed 2011 Targeted Bioassessment Results

Anne Arundel County
Department of Public Works
Watershed and Ecosystem Services and Restoration Division
Watershed Assessment and Planning




Benthic Index of Biotic Integrity

- Good
- Fair
- Poor
- Very Poor

Maryland Physical Habitat Index

- Minimally Degraded
- Partially Degraded
- Degraded
- Severely Degraded

Elevation



Drainage Areas to Sample Sites

— Major Roads
— County Streams

